Arbors for BDS core drills

Three systems are available – they allow a friction-type, convenient and secure connection between the core drill and the magnetic core drilling machine.

ACCOMMODATING OF EVERY DRILL

Arbors for BDS core drills with 19 mm $(^3/_4")$ Weldon shank



Arbors for BDS core drills with 19 mm ($^3/_4$ ") and 32 mm ($^1/_4$ ") Weldon shank



Arbors for BDS core drills with 19 mm ($^3/_4$ ") and 32 mm ($^1/_4$ ") Weldon shank



KEYLESS quick-change drilling system

ORDER NO. SPINDLE ARBOR

ZSS 200	MT 2			
ZSS 300	MT 3			
With automatic internal lubrication				
for core drills	with 19 mm $(3/4")$ Weldon shank.			
With tube and quick-lock coupling. Quick tool				
change without wrench.				



men manaan meerian labrisacion			
ORDER NO.	SPINDLE ARBOR		
For core drills	For core drills with 19 mm (3/4") Weldon shank		
ZIA 219-M	MT 2		
ZIA 319-M	MT 3		
ZIA 419-M	MT 4		
For core drills with			
32 mm (1 1/4'	') Weldon shank		
ZIA 332-M	MT 3		
ZIA 432-M	MT 4		



ORDER NO. SPINDLE ARBOR

For core drills with 19 mm (3/4") Weldon shank

ZIA 219-KN MT 2

ZIA 319-KN MT 3

ZIA 419-KN MT 4

For core drills with 32 mm (1 1/4")

Weldon shank

With tube and quick-lock coupling.

ZIA 332-KN MT 3

ZIA 432-KN MT 4



Reducing bush DIN 2185				
ORDER NO.	EXTERNAL	INTERNAL		
ZRH 210	MT 2	MT 1		
ZRH 320	MT 3	MT 2		
ZRH 430	MT 4	MT 3		



Extension sleeve DIN 2178				
EXTERNAL	INTERNAL			
MT 2	MT 2			
MT 2	MT 3			
MT 3	MT 2			
MT 3	MT 3			
	EXTERNAL MT 2 MT 2 MT 3			